

ENGINES – EXHAUST ISSUES

- Exhaust elbows: Clogs up, needs to be inspected regularly. The corrosion on the engine block side can be filled back in by a good marine engineer
- Suggested replacement option for the elbows in stainless by [HDI Marine](#).
- use Permatex Red RTV on the gasket to prevent corrosion

